Bulletin: ABIB-0801R1







Date: October 22, 2010

Bulletin Type: Service

Topic: NEW REDESIGNED 40K TANDEM CARRIERS

Affected Models:

All D344, 404, 405, DST40, 41, DSP40, 41, DSH40, DSH44 (Includes Diff Lock and Pump option models)



D344, D404(P), D405(P) FAMILY:

- Primary Gearing Standard*
- Wheel Differential Parts Standard
- Carrier Bearings Standard

*s<mark>tand</mark>ard gearing used in majority of production builds



DSP40(P), DSP41(P) FAMILY:

- High Capacity Premium Carrier Bearings
- Primary Gearing Premium Processing
- Premium Wheel Differential Parts
- Thrust Bolt Standard



DSH40(P), DSH44(P) FAMILY:

- High Capacity Premium Carrier Bearings
- Larger Primary Gearing 15.75"
- Primary Gearing Premium Processing
- Premium Wheel Differential Parts
- Premium Input & Output Shafts
- Thrust Bolt Standard